

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2020

Submitted Date:

12/10/2020

Document Number:

700702004**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 335081 _____ Ramsey, Scott _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		sgahan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282835	WELL	PR	12/31/2008	GW	045-11848	TRANT 32C-21-692	PR
282836	WELL	PR	07/16/2009	GW	045-11847	TRANT 42A-21-692	PR
282837	WELL	PR	01/04/2008	GW	045-11846	TRANT 42C-21-692	PR
282838	WELL	PR	07/16/2009	GW	045-11845	TRANT 32A-21-692	PR
291563	WELL	PR	01/02/2008	GW	045-14447	TRANT 41A-21-692	PR
291564	WELL	PR	01/02/2008	GW	045-14446	TRANT 31A-21-692	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 12/10/20 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Trant, at Location # 335081 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance which in turn can lead to tracking
- Slope next to separators need stabilization
- No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

Equipment:				corrective date
Type: Gas Meter Run	# 6			
Comment:	All meters have been calibrated on location within the past year.			
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 6			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 6			
Comment:	Braden heads have a port for manual gauge monitoring			
Corrective Action:				Date:
Type: Bird Protectors	# 7			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 6			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	chemical tank at well heads			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	OTHER	HEATED STEEL AST		,	
Comment:	375 BBL tanks and two (2) tanks are NOT heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Inspected Facilities									
Facility ID:	282835	Type:	WELL	API Number:	045-11848	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282836	Type:	WELL	API Number:	045-11847	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282837	Type:	WELL	API Number:	045-11846	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	282838	Type:	WELL	API Number:	045-11845	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291563	Type:	WELL	API Number:	045-14447	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291564	Type:	WELL	API Number:	045-14446	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
		Ditches				

Comment: • Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance which in turn can lead to tracking
 • Slope next to separators need stabilization
 • No evidence of tracking control BMP's

Corrective Action: Maintain BMP's
 Stabilize Slope next to separators
 Provide proof of tracking control BMP's

Date: 01/12/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402551892	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308201
700702009	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308196