

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2020

Submitted Date:

12/11/2020

Document Number:

688000495

**FIELD INSPECTION FORM**

Loc ID 401528 Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 55575  
Name of Operator: MCELVAIN ENERGY INC  
Address: 511 16TH STREET SUITE 700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Wilson, Amy	3036-893-0933 x315	amy.wilson@mcelvain.com	
Caplis, Chris		chris.caplis@mcelvain.com	
Hulstrom, Michelle	(303) 893-0933 X381	michelleh@mcelvain.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
102680	PIT				-	SHEIBLEY 1	EI
102681	PIT				-	SHEIBLEY 1	EI

**General Comment:**

Environmental inspection related to Rem #1519. Former landfarm oily soil requires removal and proper disposal. Contact NE EPS Rob Young ([rob.young@state.co.us](mailto:rob.young@state.co.us)) with any questions.

**Inspected Facilities**

Facility ID: 102680 Type: PIT API Number: - Status:        Insp. Status: EI

Facility ID: 102681 Type: PIT API Number: - Status:        Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: \_\_\_\_\_

Comment: Environmental inspection related to Rem #1519.

Corrective Action: Remove and properly dispose of remnant oily soils. Prepare former landfarm area for adequate reclamation per Rule 1004. Date: 01/15/2021

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402552237	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308609</a>
688000496	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308607">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308607</a>
688000497	Letter from COGCC to McElvain 4/10/2003	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308608">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308608</a>