

Inspection Photos

API: 043-06142

Operator: JAVERNICK OIL

Inspection Date: 12/16/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/16/2020

Inspection Photos



Photo 1. Facing north toward the location. The location has not established desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/16/2020

Inspection Photos



Photo 2. View of ground cover shows undesirable weeds (Kochia sp.) observed throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/16/2020

Inspection Photos



Photo 3. There is a soil pile that remains at the northwest side of the location. The soil pile needs to be replaced or removed. If soil is not from the location then the soil needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/16/2020

Inspection Photos



Photo 4. There is a metal cable at the east side of the location and soil pile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/16/2020

Inspection Photos



Photo 5. Facing south at the location. The location needs to be reclaimed and weeds need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/16/2020

Inspection Photos



Photo 6. Facing east toward the location. The location needs to be reclaimed to establish vegetation reflective of the surrounding reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/16/2020

Inspection Photos



Photo 7. Facing east toward the surrounding reference area which consists of Blue grama grassland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/16/2020