

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2020

Submitted Date:

12/21/2020

Document Number:

700702049**FIELD INSPECTION FORM**Loc ID 335276 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211376	WELL	PR	01/29/1997	GW	045-07136	GIBSON GULCH UNIT 2-31	PR
295341	WELL	PR	09/10/2008	GW	045-15730	GGU RODREICK 31A-31-691	PR
295344	WELL	PR	09/10/2008	GW	045-15733	GGU RODREICK 31D-31-691	PR
295345	WELL	PR	09/10/2008	GW	045-15734	GGU RODREICK 42D-31-691	PR
295346	WELL	PR	09/10/2008	GW	045-15735	GGU RODREICK 41A-31-691	PR
295347	WELL	PR	09/10/2008	GW	045-15736	GGU RODREICK 41C-31-691	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 12/21/20 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly GGU 2-31, at Location # 335276 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. Limited storm water inspection due to snow.

During this inspection the following possible compliance issues were observed:

- No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:	snow covered		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	500 BBLs	HEATED STEEL AST		,	
Comment:	One (1) tank is NOT heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<u>Flaring:</u>			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities						
Facility ID:	211376	Type:	WELL	API Number: 045-07136	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	295341	Type:	WELL	API Number: 045-15730	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	295344	Type:	WELL	API Number: 045-15733	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	295345	Type:	WELL	API Number: 045-15734	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	295346	Type:	WELL	API Number: 045-15735	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	295347	Type:	WELL	API Number: 045-15736	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms		Culverts				

Comment: Limited storm water inspection due to snow.
• No evidence of tracking control BMP's

Corrective Action: Provide proof of tracking control BMP's

Date: 01/21/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702054	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314570