

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date: _____

Type: Bradenhead # 1

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: _____

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: automation

Corrective Action:

Date: _____

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date: _____

Type: Bird Protectors # 2

Comment:

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,	
----------------	---	----------	----------------	--	---	--

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 289054 Type: WELL API Number: 031-08850 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Yearly bradenhead test not current. Contact COGCC engineering. 12/24/2020

Corrective Action: Comply with 341 c. Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 12/14/20 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- DIA 35-21 Company Name- City and County of Denver API- 05-031-08850 In Denver County Colorado. While there, I observed Shut in well. During this inspection the following possible compliance issues were observed: Annual Bradenhead test not current. Contact COGCC engineering Comply with 341 c. 12-24-20 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection weather conditions were cold, calm, overcast. This is a summary of inspection report.</p>	medinaj	12/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402554332	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310446
699502030	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310442