

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2020

Submitted Date:

12/16/2020

Document Number:

699303130**FIELD INSPECTION FORM**Loc ID 336210 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email            | Comment                         |
|--------------|-------|------------------|---------------------------------|
| ,            |       | cogcc@kpk.com    | <a href="#">All Inspections</a> |
| ,            |       | rwatzman@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 241444      | WELL | PR     | 09/01/2017  | GW         | 123-09233 | VONASEK 8     | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

|                           |  |                  |
|---------------------------|--|------------------|
| <b>Good Housekeeping:</b> |  |                  |
| Type                      | UNUSED EQUIPMENT                           |                  |
| Comment:                  | Unused electric panel laying on the ground |                  |
| Corrective Action:        | Comply with Rule 603.f                     | Date: 10/19/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |                       |       |
|--------------------|-----------------------|-------|
| <b>Fencing/:</b>   |                       |       |
| Type               | PUMP JACK             |       |
| Comment:           | fabricated steel pipe |       |
| Corrective Action: |                       | Date: |

|                    |                                  |       |                 |
|--------------------|----------------------------------|-------|-----------------|
| <b>Equipment:</b>  |                                  |       | corrective date |
| Type: Pump Jack    | # 1                              |       |                 |
| Comment:           |                                  |       |                 |
| Corrective Action: |                                  | Date: |                 |
| Type: Bradenhead   | # 1                              |       |                 |
| Comment:           | appears to be plumbed to surface |       |                 |
| Corrective Action: |                                  | Date: |                 |
| Type: Prime Mover  | # 1                              |       |                 |
| Comment:           | gas engine                       |       |                 |
| Corrective Action: |                                  | Date: |                 |

|                    |    |       |
|--------------------|----|-------|
| <b>Venting:</b>    |    |       |
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

|                 |  |
|-----------------|--|
| <b>Flaring:</b> |  |
| Type            |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 241444 Type: WELL API Number: 123-09233 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: braden head test is over 1 year and needs to be done annually

Corrective Action:

Date:

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>COGCC Inspection Report Summary<br/>On Wednesday 12/16/2020 at approximately 1320 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Vonasek 8 at Facility #241444 in Weld County Colorado. Follow up inspection per Doc # 699301626</p> <p>While there, I observed a well site. PR at time of inspection. Inspection is for KP Kauffman well onl as it shares location with a Kerr McGee well.</p> <p>During this inspection the following compliance issues have been addressed:<br/>General safety: PU pulley belt guard has been installed, engine belt guard is on location and needs to be installed.<br/>1002..(2).D houskeeping: stained soil under gas engine skid has been cleaned.<br/>During this inspection the following possible compliance issues were observed and is delinquent:<br/>603.f Housekeeping: Unused electric panel laying on the ground, CA date 10-19-2019. See attached photos.<br/>Location: snow covered, Weather: clear.<br/>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.<br/>This is a summary of inspection report.</p> | revasr | 12/16/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402555833    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5311693">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5311693</a> |
| 699303131    | location pics        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5311689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5311689</a> |