

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2020

Submitted Date:

12/21/2020

Document Number:

700702052**FIELD INSPECTION FORM**Loc ID 323971 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, COGCC		aaron.katz@state.co.us	
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211381	WELL	PR	09/01/2020	GW	045-07141	GIBSON GULCH UNIT 1-31	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 12/21/20 at approximately 1330, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly GGU 1-31, at Location # 323971 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. Limited storm water inspection due to snow.

During this inspection the following possible compliance issues were observed:

- No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:	snow covered			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	One (1) Braden head/s is/are open to Atmosphere and Braden head has a port for manual gauge monitoring			
Corrective Action:				Date:
Venting:				
Yes/No	YES			
Comment:	One (1) Braden head/s is/are open to Atmosphere and Braden head has a port for manual gauge monitoring			
Corrective Action:				Date:
Flaring:				

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 211381	Type: WELL	API Number: 045-07141	Status: PR	Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				

Comment: Limited storm water inspection due to snow.
• No evidence of tracking control BMP's

Corrective Action: Provide proof of tracking control BMP's

Date: 01/21/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402558619	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314583
700702057	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314573