

# Inspection Photos

Operator: Enduring Resources  
API: 067-09614  
Date: 12/22/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Some desirable vegetation observable through snow, although thorough assessment was not conducted.



Photo 3. View of project area from the southeastern corner facing center. Inset shows a closeup of cut-slope. Little desirable vegetation. Per Condition of approval for variance, operator needs to establish vegetation and stabilize cut-slopes.



Photo 4. View of reference area comprised of open pinyon and juniper woodland with gambel oak, rubber rabbitbrush, snakeweed, and Indian ricegrass.