

Inspection Photos

API: 009-06081

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 12/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06081 | Date: 12/29/2020

Inspection Photos



Photo 1. Facing west toward the location..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 12/29/2020

Inspection Photos



Photo 2. The tank is marked as not in use. Unused equipment must be removed. Additionally the berm around the tank is insufficient.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 12/29/2020

Inspection Photos



Photo 3. There is unused pipe laying at the location partially buried in dirt. Unused equipment must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 12/29/2020

Inspection Photos




Photo 4. The cover on the meter has fallen off and needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 12/29/2020

Inspection Photos



Photo 5. The well sign does not comply with 210.b.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 12/29/2020

Inspection Photos




Photo 6. The gate on the fence around the pumpjack is not maintained. Fence around the pumpjack needs maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06081 | Date: 12/29/2020