

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/28/2020

Submitted Date:

01/03/2021

Document Number:

700404795

FIELD INSPECTION FORM

Loc ID 311791 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10654
Name of Operator: LASSO OIL & GAS LLC
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ikenouye, Teri		teri.ikenouye@state.co.us	
Heil, John		john.heil@state.co.us	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228594	WELL	SI	12/01/2019	OW	103-05500	MCLAUGHLIN SR 6	SI

General Comment:

A follow up inspection of documents:
 1) FIR 700404645 dated 12-18-2020.
 2) FIR 700404676 dated 12-21-2020.

The following compliance issues were resolved:
 1) Emergency phone number is functional.

The following compliance issues are uncompleted:
 1) Report past due monthly operations on Form 7. Complete by 7-15-2020.
 2) Contact the COGCC EPS staff in reference to the oil spill. Photos 1 to 4.
 3) Gas coming out of open casing. Contact COGCC engineering. Photo 3.

This is a summary of inspection report 700404795.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume			
Crude Oil					
Comment:	Oil spill from over flowed cellar. The spill has not moved lateral since the 12-21-2020 inspection.				
Corrective Action:	Control and contain spills/releases and clean up. Contact COGCC EPS staff.			Date:	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Deadman # & Marked	# 2			
Comment:				
Corrective Action:		Date:		
Pump Jack	# 1			
Comment:	Idle at time of inspection. Power at panel is off.			
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:	Unable to determine from tapping on tank or FLIR camera if the tank is empty.				
Corrective Action:		Date:			

Paint

Condition: Adequate

Other (Content):

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:	<p>Gas venting out open casing. Gas odor on location.</p> <p>A 2nd well is located 40' north of this well that is abandon & venting gas. No API number has been assigned to this 2nd well.</p> <p>6 additional wells located 320' to 510' to the north and near this well's tank were P&A in the prior 2 months. All were open hole abandon wells venting gas. All plugged by Whiting.</p>		
Corrective Action:	Gas being vented or flared during non-upset condition without prior approval from COGCC.	Date:	

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 228594 Type: WELL API Number: 103-05500 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. The well was producing until 12-21-2020 when the inspector shutoff the power at the panel.

Corrective Action: Submit required Form 7(s) to COGCC.

Date: 07/15/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Snow on ground.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

