

Inspection Photos

API: 009-05117

Operator: TINDALL OPERATING COMPANY

Inspection Date: 12/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-05117 | Date: 12/29/2020

Inspection Photos



Photo 1. Facing west toward the access road. It appears the road may have been seeded however. It does not appear the road was decompacted by cross ripping to 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05117 | Date: 12/29/2020

Inspection Photos



Photo 2. Facing southwest toward the location. The location has areas with no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05117 | Date: 12/29/2020

Inspection Photos



Photo 3. There is pipe risers and equipment that remain at the location. All equipment should have been removed within 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05117 | Date: 12/29/2020

Inspection Photos



Photo 4. Facing east toward the location. It appears the road may have been seeded however. It does not appear the location was decompacted by cross ripping to 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05117 | Date: 12/29/2020