



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**A.C. McLaughlin JR 11**

**API: 05-103-05577**

**Inspection: 700404802**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Pump jack.**

**A.C. McLaughlin JR 11**

**API: 05-103-05577**

**Inspection: 700404802**



40.10469, -108.85011, 5186.6ft, 95°  
12/28/2020 11:55:27 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Well.**

**A.C. McLaughlin JR 11**

**API: 05-103-05577**

**Inspection: 700404802**





40.10469, -108.85009, 5188.2ft, 338°  
12/28/2020 12:02:37 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Well. Gas leak.**

**A.C. McLaughlin JR 11**

**API: 05-103-05577**

**Inspection: 700404802**



40.10465, -108.85009, 5190.6ft, 6°  
12/28/2020 12:02:56 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Power panel.**

**A.C. McLaughlin JR 11**

**API: 05-103-05577**

**Inspection: 700404802**



