


**Inspection Photos**  
**Location Name: Champlin 78 Amoco B 1**  
**Location ID: 319896**



**Pic 1 weeds**



**Pic 2**

**Inspection Photos**  
**Location Name: Champlin 78 Amoco B 1**  
**Location ID: 319896**



**Pic 3 weeds around pump jack**



**Pic 4 stained soil / weeds / no BMP under chemical tank**


## Inspection Photos

Location Name: Champlin 78 Amoco B 1

Location ID: 319896



**Pic 5 stained soil / no BMP under chemical tank/ weeds**



**Pic 6 stained soil**

## Inspection Photos

Location Name: Champlin 78 Amoco B 1

Location ID: 319896

Jan 4, 2021 at 1:38:50 PM  
39.948170,-104.624184  
COGCC



**Pic 7 stained soil / no BMP under chemical tanks / weeds**