

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/22/2020

Submitted Date:

12/29/2020

Document Number:

699802302

**FIELD INSPECTION FORM**

Loc ID 316278 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 200502  
Name of Operator: 31 OPERATING  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260270	WELL	PR	09/10/2004	GW	103-10141	WRD UNIT 32-12	SI

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Tuesday 12/22/20 I, Inspector Corey De Paolo, Conducted, a safety and compliance Inspection at 31 OPERATING WRD UNIT-62N96W /32NENW, Location #316278 in Rio Blanco County Colorado.  
During this inspection the following possible compliance issues were observed: Debris on location. See photo #2518 with a corrective action date of 1/12/21. Supply gas to separator leaking due to valve at wellhead being left open. See photo #2519. An attempt was made to contact the operator at 9:12 A.M. on 12/22/20 with no answer and no voice mail available with a corrective action date of 12/23/20.  
  
A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
	Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris on location. See photo #2518		
Corrective Action:	Production facilities, shall be kept free of debris. Remove all debris from location.		Date: <u>01/12/2021</u>

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST		,	
Comment:	One tank appeared to be full and the other half full.					

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Supply gas to separator leaking due to valve at wellhead being left open. See photo #2519. An attempt was made to contact the operator at 9:12 A.M. on 12/22/20 with no answer and no voice mail available.		
Corrective Action:	The unnecessary or excessive venting of natural gas produced from a well is prohibited.	Date:	12/23/2020

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 260270 Type: WELL API Number: 103-10141 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Ditches						
Berms						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402562626	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318043">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318043</a>
699802303	Photos for Insp. #699802302	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5318033</a>