

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/29/2020

Submitted Date:

12/30/2020

Document Number:

690200980**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
LEVENGOD JOHN		jlevengood07@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429852	GAS COMPRESSO R STATION	AC			-	Walsh/Bishop Gas Compressor	AC

**General Comment:**

This is a location inspection.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	The QTR QTR and section is not accurate on the sign. Sign not posted or information inaccurate at well(s) or battery.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/01/2021

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	The perimeter of the location consists of tall weeds (Kochia) debris which is a fire hazard. The weeds around the perimeter of the location need to be cut and removed.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/14/2021
Type	STORAGE OF SUPL		
Comment:	There is unused tanks and supplies stored at the backside of the metal panel wall. Unused supplies and equipment must be removed.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/14/2021
Type	STORAGE OF SUPL		
Comment:	There are numerous containers and supplies that are laying on the ground with no containment and do not appear to be in use. Unused supplies and equipment must be removed.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/14/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
Lube Oil			
Comment:	There is oil stained soil near the black containers which appear to be lube oil (Photo 5). There is also oil in the containment of the white tank which appears to have spilled over on the ground (Photo 6).		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. Require appropriate cleanup.		Date: 12/31/2020
Crude Oil	Tank		
Comment:	There is oil stained soil near the produced water tank.		
Corrective Action:	"Properly dispose of oily waste in accordance with Rule 907.e and contact area COGCC EPS"		Date: 01/20/2021

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402563813	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319026">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319026</a>
690200981	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319024">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319024</a>