



Whiting Oil & Gas Corporation

HORSETAIL 02D-0204 CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 437025
Sec 2 T10N R57W

1/5/21



Impacted soils no longer at Wellhead or Exhaust



Whiting Oil & Gas Corporation

HORSETAIL 02D-0204 CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 437025

Sec 2 T10N R57W

1/5/21



Impacted soils no longer along the side of Pump Jack or at Scrub Pot



Whiting Oil & Gas Corporation

HORSETAIL 02D-0204 CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 437025
Sec 2 T10N R57W

1/5/21



Impacted soils no longer at the Pump Jack Engine