

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/07/2021

Submitted Date:

01/07/2021

Document Number:

699802373

FIELD INSPECTION FORMLoc ID 334086 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , Caerus | | COGCC.inspections@caerus oilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 277172 | WELL | PR | 08/31/2007 | GW | 045-10613 | MURRAY 1-24A | PR |
| 285603 | WELL | PR | 08/01/2020 | GW | 045-12522 | MURRAY 1-24B | PR |

General Comment:

COGCC Inspection Report Summary
 On Thursday 1/7/21 at approximately 12:00 hours, I, Inspector Corey De Paolo,
 Conducted, an on-site inspection at CAERUS PICEANCE LLC MURRAY-68S96W /1SESW,
 Location #334086 in Garfield County Colorado.
 While there, I observed normal production operations.
 This is a summary of inspection report.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-----|-------|--|
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--------|-------|--|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------------------------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Hog panels | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Barbed wire fence around location | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--------------------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # | | |
| Comment: | Wells located on a separate location | | |

| | | | |
|-----------------------------------|-----|-------|--|
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 4 | OTHER | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 265 bbl | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 277172 Type: WELL API Number: 045-10613 Status: PR Insp. Status: PR**Producing Well**Comment: Produing

Corrective Action:

Date:

Facility ID: 285603 Type: WELL API Number: 045-12522 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Ditches | | | | |
| Ditches | | | | | | |
| Berms | | | | | | |
| | | Berms | | | | |
| | | Gravel | | | | |
| Gravel | | | | | | |
| | | Culverts | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|----------|------------|
| This inspection was conducted simultaneously with inspection #699802375 due to the location being a dual lease. | depaoloc | 01/07/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 699802374 | Photos for Insp. #699802373 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5324876 |