

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2021

Submitted Date:

01/09/2021

Document Number:

688309390

FIELD INSPECTION FORM

Loc ID: 317281 Inspector Name: Sherman, Susan On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10690
Name of Operator: IMPETRO RESOURCES LLC
Address: 2820 LOGAN DRIVE
City: LOVELAND State: CO Zip: 80538

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gibson, Rick	970-768-6880	rtgibson01@msn.com	
Bradley, Sam	970-593-8626	sbradley.impetro@gmail.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237714	WELL	PR	02/01/2019	OW	121-10217	MARICK STATE 2	PR

General Comment:

Pit Inspection, no oil on pit, no photos taken

Inspected Facilities

Facility ID: 237714 Type: WELL API Number: 121-10217 Status: PR Insp. Status: PR

Producing Well

Comment: [PR 11/1/2020 production reported to COGCC database.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action Date: _____

Fencing:

Fencing Type: None Fencing Condition:

Comment: crop field

Corrective Action Date: _____

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action Date: _____

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action Date: _____