


Ward and Sons, Alfred - COGCC Inspection Photos

Location: Pierce 1 OL Flowline Release

Spill ID #478817 Date 01/08/2021



Wellhead signage



Pierce 1 wellhead (Shut in); No OOSLAT

Ward and Sons, Alfred - COGCC Inspection Photos

Location: Pierce 1 OL Flowline Release

Spill ID #478817 Date 01/08/2021



View of excavation at off location flowline release; looking NE from wellhead to battery.



View from trench excavation at spill point; looking SW toward Pierce 1 well.

Ward and Sons, Alfred - COGCC Inspection Photos

Location: Pierce 1 OL Flowline Release

Spill ID #478817 Date 01/08/2021



Flowline pipe exposed in trench excavation (yellow jacket pipe/ yellow external coating) .



View of surface impacts at flowline release; looking NE toward Pierce battery.

Ward and Sons, Alfred - COGCC Inspection Photos

Location: Pierce 1 OL Flowline Release

Spill ID #478817 Date 01/08/2021



**View of Pierce 1 off location flowline exposed in excavation;
Significant external coating damage observed.**



**Larger black pipe exposed at NE end of trench excavation;
Excavation equipment scored pipe coating.**