

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2021

Submitted Date:

01/06/2021

Document Number:

696104133

FIELD INSPECTION FORM

Loc ID 306293 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287599	WELL	TA	05/14/2020	OW	123-24372	GABEL USX AB 21-11	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.554809 / -104.563667

Abandoned Centralized Battery formerly served 3 Location IDs.
(417660, 306293, 420534).
(Well(s): 3: Temporarily Abandoned | TA).

Location

Lease Road:

	Type Access		
comment:	Adequate.		
Corrective Action:			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:

						corrective date
Type: Emission Control Device	# 0					
Comment:	Battery Abandoned. Equipment removed.					
Corrective Action:						Date:
Type: Gas Meter Run	# 0					
Comment:	Battery Abandoned. Equipment removed.					
Corrective Action:						Date:
Type: Plunger Lift	# 1					
Comment:						
Corrective Action:						Date:
Type: Bradenhead	# 1					
Comment:	Appears plumbed to surface.					
Corrective Action:						Date:
Type: Horizontal Heated Separator	# 0					
Comment:	Battery Abandoned. Equipment removed.					
Corrective Action:						Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				

Comment: [Battery Abandoned. Equipment removed.](#)

Corrective Action: _____ Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: _____

Corrective Action: _____ Date: _____

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				

Comment: [Battery Abandoned. Equipment removed.](#)

Corrective Action: _____ Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: _____

Corrective Action: _____ Date: _____

Venting:

Yes/No	NO		
Comment:	_____		
Corrective Action:	_____		Date: _____

Flaring:

Type	_____		
Comment:	_____		
Corrective Action:	_____		Date: _____

Inspected Facilities

Facility ID: 287599 Type: WELL API Number: 123-24372 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Battery Abandoned: All Equipment Removed.
 COGCC records indicate last production: 12/2016.
 SI/TA well per variance doc. #401474555. (NOBLE).
 Yellow LTSI tag for SI/TA status present at wellsite.
 Locked-Out, Tagged-Out | LOTO.

 Form 4 Sundry doc. #402394244, Temporarily Abandoned | TA status date: 01/18/2019.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: No record of Brhd test within last 12 months. Refer to Rule 206.
 Submit current Brhd test. Comply w/ Rule 206.
 Contact COGCC Engineering.
 Corrective Action date: 04/06/2021. 04/06/2021

Corrective Action: **Submit current Brhd test. Comply w/ Rule 206.**
Contact COGCC Engineering. Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 01/05/2021 at approximately 12:38 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: GABEL USX AB-67N64W /21NESW Location ID: 306293 Well Name: Gabel USX AB 21-11 API: 05-123-24372 Location County: Weld County, Colorado Weather: Mostly cloudy, patchy snow cover from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.554809 / -104.563667</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs. (417660, 306293, 420534). (Well(s): 3: Temporarily Abandoned TA).</p> <p>During this inspection the following possible compliance issues were observed: 1.) No record of Brhd test within last 12 months. Refer to Rule 206. Submit current Brhd test. Comply w/ Rule 206. Contact COGCC Engineering. Corrective Action date: 04/06/2021.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402568501	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5323676
696104134	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5323674