

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2021

Submitted Date:

01/06/2021

Document Number:

700702153

FIELD INSPECTION FORMLoc ID 323982 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|----------|
| , Grizzly | | aaxelson@grizzlyenergyllc.com | |
| , Grizzly | | sgghan@grizzlyenergyllc.com | SR. EH&S |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 211403 | WELL | PR | 07/27/1997 | GW | 045-07163 | GIBSON GULCH UNIT 3-31 | PR |

General Comment:**COGCC Inspection Report Summary**

On Tuesday 1/6/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly GGU 3-31, at Location # 323982 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. Battery sign is located at separators.

During this inspection the following possible compliance issues were observed:

- No evidence of tracking control BMP's
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

| | | | |
|--------------------|--------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | snow covered | | |
| Corrective Action | L | Date: | |

Overall Good: ☐

| | | | |
|----------------------|--|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Battery sign is located at separators. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|-----|-------------|
| Emergency Contact Number: | | |
| Comment: | 911 | |
| Corrective Action: | | Date: _____ |

| | | | |
|---------------------------|--------|-------|--|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|---------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | All meters have been calibrated on location within the past year | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Braden head has a port for manual gauge monitoring and is tied into sales. | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 211403 | Type: | WELL | API Number: | 045-07163 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | producing | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------------|
| | | | | | | |
| Comment: Limited storm water inspection due to snow cover No evidence of tracking control BMP's | | | | | | Date: 02/08/2021 |
| Corrective Action: Provide proof of tracking control BMP's | | | | | | |
| Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT | | | | | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402568418 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5323628 |
| 700702161 | photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5323620 |