

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/12/2021

Submitted Date:

01/12/2021

Document Number:

699502129

**FIELD INSPECTION FORM**

Loc ID: 320342 Inspector Name: MEDINA, JUSTIN On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10395  
Name of Operator: GOODWIN ENERGY MANAGEMENT LLC  
Address: 740 S OGDEN STREET  
City: DENVER State: CO Zip: 80209

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Goodwin, Scott	(303) 478-4800	scottgoodwinjr@gmail.com	
GOODWIN, SCOTT	303-881-2482	sosoil2gas@yahoo.com	owner

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203506	WELL	PR	08/11/2010	OW	001-09066	SATTERFIELD 1	PR

**General Comment:**



Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	shares containment with oil tank				
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 203506 Type: WELL API Number: 001-09066 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Annual bradenhead test is not current. Contact COGCC engineering 01/22/2021

Corrective Action: Comply with 341 c Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On 1/12/21 at approximately 1500I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Satterfield 1                      Company Name- Gemco                      API- 05-001-320342                      In Adams County Colorado.                      While there, I observed Producing well                      During this inspection the following possible compliance issues were observed:                      Annual bradenhead test is not current. Contact COGCC engineering.                      Comply with 341 c 1/22/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      At time of inspection weather conditions were overcast, warm, recent snow.                      This is a summary of inspection report.</p>	medinaj	01/12/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502130	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328477">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328477</a>