

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/13/2021

Submitted Date:

01/13/2021

Document Number:

699303245

**FIELD INSPECTION FORM**
 Loc ID 323619 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
,		rwatzman@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245490	WELL	PR	03/01/2020	OW	123-13285	MCCONAHAY 33-34	PR
477181	TANK BATTERY	AC	07/14/2020		-	Mcconahay 33-34 battery	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	trash in Seperator house		
Corrective Action:	comply with Rule 603.f	Date:	01/27/2021
Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Comply with Rule 907.e	Date:	08/15/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Ancillary equipment	# 2		
Comment:	automation, electric panel		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	appears to be plumbed to surface	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	electric motor	
Corrective Action:		Date:
Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		,
Comment:	open top tank with screening as wildlife protection as shown in attached photo tank labeled as 100 bbls but appears larger				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:			
Corrective Action:			Date:
<b><u>Wells Served By Facilities Above</u></b>			
API Number		AirsID	
123-13285			
<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 245490 Type: WELL API Number: 123-13285 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: test is over 1 yr. and needs to be performed annually and well monitored monthly, submit bradenhead test information to COGCC engineering.

Corrective Action:

Date:

Facility ID: 477181 Type: TANK API Number: - Status: AC Insp. Status: AC

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary  
On Wednesday 1/13/2021 at approximately 1455 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:  
  
McConahay 33-34 at API #05-123-13285 in Weld County Colorado.  
While there, I observed a wellsite and tank battery,  
During this inspection the following possible compliance issues were observed:  
603.f Housekeeping: Stained soil around WH, CA date 8-15-2020 see photos 2 and 10.  
603.f Housekeeping: trash in seperator house CA date 1-27-2021 see photos 7, 8 and 9.  
See attached photos.  
Location: muddy, Weather: cloudy.  
A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

revasr

01/13/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303246	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329381">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329381</a>