

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402574970

Date Received:

01/14/2021

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10734

Name of Operator: HIGH RIVER RESOURCES OPERATING LLC

Address: 3838 OAK LAWN AVE SUITE 710

City: DALLAS State: TX Zip: 75219

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Amy Archuleta

Phone

505-320-6917

Email

aarchuleta@highriverllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902730

Inspection Date: 01/11/2021

FIR Submit Date: 01/13/2021

FIR Status: _____

Inspected Operator Information:

Company Name: HIGH RIVER RESOURCES OPERATING LLC

Company Number: 10734

Address: 3838 OAK LAWN AVE SUITE 710

City: DALLAS State: TX Zip: 75219

LOCATION - Location ID: 311948

Location Name: IGNACIO 33-7-N33N7W Number: 32SWSW County: LA PLATA

Qtrqr: SWS Sec: 32 Twp: 33N Range: 7W Meridian: N
W

Latitude: 37.056660 Longitude: -107.637790

FACILITY - API Number: 05-067- -00 Facility ID: 215711

Facility Name: IGNACIO 33-7 Number: 14-32

Qtrqr: SWS Sec: 32 Twp: 33N Range: 7W Meridian: N
W

Latitude: 37.056660 Longitude: -107.637790

CORRECTIVE ACTIONS:

2 CA# 145845

Corrective Action: -Stormwater controls need to be installed to stabilize erosion within the project area. Corrective action is back-dated to original corrective action date (5/17/2019) to document duration of non-compliance.

Date: 05/17/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Inspection Document: 402574970

As noted on the Inspection, this inspection was submitted to the previous owner (Enervest) in 2019. As the new

Operator
Comment:

operator, we were unaware this work was not complete. That should be noted on this inspection as well for documentation of compliance.
This location is on a shared pad with Red Willow Production Company. They have two wells on this location. The Ignacio 33 7 #32-4 API: 05-067-08503 and the Ignacio 33 7 #32-5 API: 067-09198. After reviewing the site, High River believes this should be a joint effort. We are unclear on how you determine which operator is responsible for erosion issues on a shared pad. RWPC's location has not been inspected since 2014. I have attached an aerial photo for reference of equipment ownership and erosion issues.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed: _____

Title: Regulatory Supervisor

Date: 1/14/2021 12:35:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402575061	Aerial View
-----------	-------------

Total Attach: 1 Files