

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2021

Submitted Date:

01/14/2021

Document Number:

688800847

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 325536 _____ Hughes, Jim _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
 3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
,	970-563-4000	maralextech@gmail.com	All Inspections
Heil, John		john.heil@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214965	WELL	PR	12/03/2012	GW	067-06570	GOSNEY 1	EI
463850	Domestic Tap	AC	04/10/2019		-	Domestic Tap 14NWNW	EI

General Comment:

On January 5, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Gosney #1. For the most recent field inspection report of this facility, please refer to document #687904955.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to separator shack.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Tank battery signs have previous operator and emergency contact information listed.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/15/2021
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Two track hoes and a loader stored on site.		
Corrective Action:	Comply with Rule 603.f.	Date:	01/29/2021
Type	UNUSED EQUIPMENT		
Comment:	Cables near well head.		
Corrective Action:	Comply with Rule 603.f.	Date:	01/29/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Jersey barriers protecting well head and separator.		
Corrective Action:		Date:	
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:		Date:	
Type:	Deadman # & Marked	# 4	
Comment:	NE marker is down.		

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Domestic tap.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		37.193111,-107.582173
Comment:	Tank battery on #1A location.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
067-09255
067-06729
067-09798
067-09507
067-06570

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 214965 Type: WELL API Number: 067-06570 Status: PR Insp. Status: EI

Facility ID: 463850 Type: Domestic Tap API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Drip pot on south load out line.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On January 5, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Gosney #1. For the most recent field inspection report of this facility, please refer to document #687904955.</p> <p>Heavy equipment is being stored on location. Unused cables are being stored near the well head. A section of abandoned flow line, noted in previous inspections, was observed off of the eastern edge of the location. Comply with Rule 603.f. Corrective action dates are listed within this document.</p> <p>The remote tank battery signs have the previous operator and emergency contact information listed.</p>	hughesjo	01/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402574801	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329829
688800848	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329824