

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/20/2021

Submitted Date:

01/20/2021

Document Number:

701101052

**FIELD INSPECTION FORM**Loc ID 324184 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262339	WELL	PR	08/01/2013	GW	045-08016	CHEVRON GM 42-17	PR
282744	WELL	PR	07/23/2006	GW	045-11819	CHEVRON GM 332-17	PR
282745	WELL	PR	01/20/2006	GW	045-11820	CHEVRON GM 443-17	PR
282746	WELL	PR	12/01/2010	GW	045-11821	CHEVRON GM 342-17	PR
282747	WELL	PR	07/23/2006	GW	045-11822	CHEVRON GM 442-17	PR

**General Comment:****COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W 17SENE, Location # 324184 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 5		corrective date
Comment:	Braden head accessible for monitoring.		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 5	
Comment:		
Corrective Action:		Date:
Type: Dehydrator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	262339	Type:	WELL	API Number:	045-08016	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282744	Type:	WELL	API Number:	045-11819	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282745	Type:	WELL	API Number:	045-11820	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282746	Type:	WELL	API Number:	045-11821	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282747	Type:	WELL	API Number:	045-11822	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location shows signs of lack of stabilization BMP's in some areas \(rutting is present\).](#)

Corrective Action: [Install, maintain or provide documentation of post construction management plan or BMP's](#)

Date: 02/04/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101053	Inspection 701101052 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334406">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334406</a>