

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/21/2021

Submitted Date:

01/21/2021

Document Number:

701101069

FIELD INSPECTION FORM

Loc ID 335206	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 10 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258628	WELL	PR	09/01/2020	GW	045-07645	UNOCAL 24-16D	PR
258630	WELL	SI	09/01/2019	GW	045-07647	UNOCAL 14-16D	SI
258631	WELL	PR	09/01/2020	GW	045-07648	UNOCAL 13-16D	PR
288392	WELL	PR	09/01/2020	GW	045-13242	UNCOAL-ENCANA 14D-16D	PR
288393	WELL	PR	09/01/2020	GW	045-13241	UNOCAL-ENCANA 14B-16D	PR
288394	WELL	PR	09/01/2020	GW	045-13240	UNOCAL-ENCANA 14A-16D	PR
288401	WELL	PR	09/01/2020	GW	045-13233	UNCOAL-ENCANA 24B-16D	PR
288402	WELL	PR	09/01/2020	GW	045-13232	UNOCAL-ENCANA 24D-16D	PR

General Comment:**COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at CAERUS PICEANCE LLC, UNOCAL-66S96W 16LOT 13, Location # 335206 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

Location shows signs of lack of stabilization BMP's in some areas (rutting is present). Storm water stalling at intersection of county road and access road.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities				
Facility ID: 258628	Type: WELL	API Number: 045-07645	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 258630	Type: WELL	API Number: 045-07647	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment:				
Corrective Action:		Date:		
Facility ID: 258631	Type: WELL	API Number: 045-07648	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 288392	Type: WELL	API Number: 045-13242	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 288393	Type: WELL	API Number: 045-13241	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 288394	Type: WELL	API Number: 045-13240	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 288401	Type: WELL	API Number: 045-13233	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 288402	Type: WELL	API Number: 045-13232	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:		Date:		

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Ditches	Pass			
		Culverts	Pass			
Ditches	Pass					
		Gravel	Pass			
				Vehicle Tracking	Fail	

Comment: Location shows signs of lack of stabilization BMP's in some areas (rutting is present).
Storm water stalling at intersection of county road and access road.

Corrective Action: Install, maintain or provide documentation of post construction management plan or BMP's

Date: 02/05/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101070	Inspection 701101069 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334954