

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/20/2021

Submitted Date:

01/20/2021

Document Number:

700702186

FIELD INSPECTION FORM

Loc ID 335156	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 14 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10531 Name of Operator: GRIZZLY OPERATING LLC Address: 5847 SAN FELIPE #3000 City: HOUSTON State: TX Zip: 77057				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291462	WELL	PR	12/18/2007	GW	045-14382	SPECIALTY 21A-28-692	PR
291479	WELL	PR	12/20/2007	GW	045-14384	SPECIALTY 24A-21-692	PR
291480	WELL	PR	12/19/2007	GW	045-14385	SPECIALTY 21D-28-692	PR
291481	WELL	PR	12/20/2007	GW	045-14386	SPECIALTY 24C-21-692	PR
291482	WELL	PR	12/18/2007	GW	045-14387	SPECIALTY 21B-28-692	PR
291483	WELL	PR	12/18/2007	GW	045-14388	SPECIALTY 21C-28-692	PR
292115	WELL	PR	12/20/2007	GW	045-14599	SPECIALTY 14A-21-692	PR
292116	WELL	PR	08/01/2019	GW	045-14598	SPECIALTY 14C-21-692	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 1/20/2021 at approximately 1130, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Specialty 21A, at Location # 335156 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Provide proof of tracking control BMP's
 - Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 8		corrective date
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	291462	Type:	WELL	API Number:	045-14382	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291479	Type:	WELL	API Number:	045-14384	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291480	Type:	WELL	API Number:	045-14385	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291481	Type:	WELL	API Number:	045-14386	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291482	Type:	WELL	API Number:	045-14387	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291483	Type:	WELL	API Number:	045-14388	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292115	Type:	WELL	API Number:	045-14599	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292116	Type:	WELL	API Number:	045-14598	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover
 1. Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance
 2. Provide proof of tracking control BMP's

Corrective Action: 1. Install or repair required BMPs in order to achieve stabilization on location
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 02/22/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402579866	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334213
700702191	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5334209