

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4SENW

Location ID: 334697



Photo #2706 from entrance to location.



Photo #2707 Rutting present on location due to lack of stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4SENW

Location ID: 334697



Photo #2708 Rutting present on location due to lack of stabilization.



Photo #2709 Rutting present on location due to lack of stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4SENW

Location ID: 334697



Photo #2710 Rutting present on location due to lack of stabilization.