

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNW

Location ID: 311547



Photo #2711 from entrance to location.



Photo #2712 Wellhead sign weathered and not legible.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNW

Location ID: 311547



Photo #2715 Ruts present on location due to lack of stabilization.



Photo #2716 Ruts present on location due to lack of stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNW

Location ID: 311547



Photo #2717 Ruts present on location due to lack of stabilization.