

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/21/2021

Submitted Date:

01/28/2021

Document Number:

690102268

FIELD INSPECTION FORMLoc ID 323578 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Knop, Max		mknop@kpk.com	
		cogcc@kpk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245427	WELL	PR	10/01/2018	OW	123-13222	LONGMONT FARMS UNIT 5	EG
479267	SPILL OR RELEASE	AC			-	Longmont Farms Unit #5 Flowline	EG

General Comment:

COGCC engineering integrity inspection performed on January 21st, 2021 in response to initial form 19 spill report Doc #402579101 received on 01/20/2021 that outlines: Small surface staining observed by KPK along the Longmont Farms Unit #5 flowline. Associated well was immediately shut in. Further investigation is necessary to determine root cause of release and quantify volume of fluids released.

Corrective Actions identified during this field inspection are outlined in the flowline section of report. Photos uploaded.

Inspected Facilities

Facility ID: 245427 Type: WELL API Number: 123-13222 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: No Age: 20+ Yrs Contents:

Integrity Summary

Failures: Spills: Yes Repairs Made: No
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: COGCC Integrity Inspection performed on 1/21/2021; No KPK personnel were on location at time of field inspection. The Longmont Farms Unit #5 well was observed shut in at wellhead (No OOSLAT/ tagout). The area of the off location flowline release has been marked (staked/ flagged); initial spill response completed (surface area grubbed). Excavation work to expose the failed flowline has not been initiated; remediation work and flowline repairs are pending.

Corrective Action: Provide information requested below to COGCC Integrity Inspector (via email) and add to Corrective Actions section of COGCC supplemental form 19 spill report (pertaining to compliance of COGCC series 1100 flowline regulations):
 1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/ operator determination)
 2) Measures taken to prevent a recurrence of failure (1102.I Corrosion Control)
 3) Description of flowline repair/replacement work completed (1102.j. Repair)
 4) Perform flowline pressure testing to verify integrity of repairs/ reconnections completed prior to returning the Longmont Farms Unit 5 OLF to service (1102.j.4 and 1102.O). Contact COGCC Integrity Inspector with schedule of repair work and followup pressure testing. Upload flowline pressure testing chart/ data to COGCC Form 19 subsequent.
 5) Ensure OOSLAT (valves tagged out) in place to prevent unintentional release per 1102.j.7 (prior to and during time of repair).

Date: 03/01/2021

Facility ID: 479267 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
690102269	Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339001
690102270	View N from wellhead to release (Staked)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339002
690102271	View of impacted area (staked/ grubbed); S to well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339003