

**TEP ROCKY MOUNTAIN LLC  
UNOCAL-66S96W 35SWSW  
Location # 334773**



**Access road shows signs of lack of stabilization BMP's in some areas (rutting is present). No tracking bmps observed for access road.**

**TEP ROCKY MOUNTAIN LLC  
UNOCAL-66S96W 35SWSW  
Location # 334773**



**Access road shows signs of lack of stabilization BMP's in some areas (rutting is present). No tracking bmps observed for access road.**

**TEP ROCKY MOUNTAIN LLC  
UNOCAL-66S96W 35SWSW  
Location # 334773**



**Access road shows signs of lack of stabilization BMP's in some areas (rutting is present). No tracking bmps observed for access road.**

**TEP ROCKY MOUNTAIN LLC  
UNOCAL-66S96W 35SWSW  
Location # 334773**



**Tracking visible on shoulder to white line.**

**Sediment moving on to shoulder of CR215**

**TEP ROCKY MOUNTAIN LLC  
UNOCAL-66S96W 35SWSW  
Location # 334773**



**Sediment moving on to shoulder of CR215**



**Storm water bmps are failing at access  
right away and CR215.**

**TEP ROCKY MOUNTAIN LLC  
UNOCAL-66S96W 35SWSW  
Location # 334773**



**Storm water bmps are failing at access right away and CR215.**



**Washing and eroding of shoulder of road.**

**TEP ROCKY MOUNTAIN LLC  
UNOCAL-66S96W 35SWSW  
Location # 334773**



**Drainage merging with access road ditch check dam. Low water crossing across road.**



**Inadequate ditch for flow.**

**TEP ROCKY MOUNTAIN LLC  
UNOCAL-66S96W 35SWSW  
Location # 334773**



**Catch basin in brush near post marked A.**



**Basin is inadequate size**