

Inspection Photos  
Operator: Logos  
API: 067-08104  
Date: 1/29/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Location largely snow covered. Taller perennial vegetation such as sand dropseed, smooth brome, and sagebrush observed through snow. Unused equipment and materials stored along the western edge.



Photo 3. View of the eastern project area from the northeastern corner facing southward.





Photo 4. View of the reference area comprised of pinyon and juniper woodland with sagebrush in the understory. Snow cover prevents identification of grasses and forbs.