

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2021

Submitted Date:

01/26/2021

Document Number:

700702225**FIELD INSPECTION FORM**
 Loc ID 336014 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278175	WELL	PR	12/20/2009	GW	045-10845	RIVER RANCH A4	PR
278176	WELL	PR	11/01/2020	GW	045-10846	RIVER RANCH A6	PR
278179	WELL	PR	01/15/2008	GW	045-10849	RIVER RANCH A1	PR
284272	WELL	PR	03/20/2012	GW	045-12124	RIVER RANCH A5	PR
284276	WELL	PR	12/20/2009	GW	045-12120	RIVER RANCH A3	PR

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 1/26/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa River Ranch A, at Location # 336014 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. All C/A's from previous inspection document # 700701871 have been completed. Operator has provided documentation of their Best Management Practices for Pad Surface Stabilization.

During this inspection the following possible compliance issues were observed:

- Tank battery signage is missing information and located at entrance of location

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	snow covered		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	• Tank battery signage is missing information and located at entrance of location		
Corrective Action:	Comply with rule 605.e	Date:	04/26/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 278175 Type: WELL API Number: 045-10845 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 278176 Type: WELL API Number: 045-10846 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 278179 Type: WELL API Number: 045-10849 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 284272 Type: WELL API Number: 045-12124 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 284276 Type: WELL API Number: 045-12120 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Comment: <a href="#">Limited storm water inspection due to snow cover Operator has provided documentation of their Best Management Practices for Pad Surface Stabilization.</a>						Date: _____
Corrective Action: _____						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402583756	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5337518">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5337518</a>
700702229	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5337512">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5337512</a>