

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2021

Submitted Date:

02/01/2021

Document Number:

695103930**FIELD INSPECTION FORM**Loc ID 308563 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274356	WELL	PR	04/15/2005	GW	071-08231	SAMSON 11-35	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Phone 3: AREA OF IMPACTED SOIL NEAR PRIME MOVER ENGINE SKID UNDER RADIATOR. Phone 4: AREA OF IMPACTED SOIL ACROSS FROM GAS SCRUBBER/SEPARATOR ON COMPRESSOR. IT APPEARS THAT GAS SCRUBBER/SEPARATOR ON COMPRESSOR SKID IS BEING DRAINED ON THE GROUND. Phone 5: AREA OF IMPACTED SOIL NEAR WELLHEAD.

Corrective Action:

COMPLY WITH RULE 906.

Date: 03/03/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

1

Comment:

CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Phone 8: BRADENHEAD IS NOT PLUMBED TO SURFACE.

Corrective Action:

COMPLY WITH RULE 341.

Date: 03/03/2021

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities				
Facility ID: 274356	Type: WELL	API Number: 071-08231	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Phone 6: APPEARS TO BE ANTIFREEZE IN PRIME MOVER ENGINE SKID. Phone 7: APPEARS TO BE OIL EITHER DRAINED OR LEAKED INTO COMPRESSOR SKID.

Corrective Action: COMPLY WITH THE GENERAL RULES OF THE OIL AND GAS ACT & SB481. (DO NOT DRAIN ANY NON E&P WASTE IN SKIDS OR ON GROUND REMOVE ANY UNINTENDED LEAKS OF NON E&P WASTE INTO SKIDS IMMEDIATELY UPON DISCOVERY. CA DATE 2-6-21.

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	289787	2057218	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103931	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342227