

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2021

Submitted Date:

02/02/2021

Document Number:

700702257

FIELD INSPECTION FORM

Loc ID 335538 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 950 17TH STREET, SUITE 1900
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 20 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291065	WELL	PR	11/01/2020	GW	045-14284	VALLEY FARMS F2	PR
291066	WELL	PR	11/01/2020	GW	045-14285	VALLEY FARMS F3	PR
291067	WELL	PR	11/01/2020	GW	045-14286	VALLEY FARMS F5	PR
291072	WELL	PR	11/01/2020	GW	045-14289	VALLEY FARMS F7	PR
291073	WELL	PR	11/01/2020	GW	045-14290	VALLEY FARMS F1	PR
296414	WELL	PR	11/01/2020	GW	045-16011	VALLEY FARMS F8	PR
296415	WELL	PR	07/11/2013	GW	045-16012	VALLEY FARMS FEDERAL F14	PR
301818	WELL	PR	04/04/2013	GW	045-18286	Valley Farms F-1H	PR
301819	WELL	XX	04/27/2018	LO	045-18287	Valley Farms F21	XX

General Comment:

COGCC Inspection Report Summary

On Tuesday 2/2/2021 at approximately 1400, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa Valley Farms F, at Location # 335538 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. Some of the C/A's from previous inspection document # 700701947 have been completed. Operator has provided documentation of their Best Management Practices for Pad Surface Stabilization.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage is missing information and located at entrance
2. Some staining/paraffin under tank valves
3. Location still shows signs of lack of stabilization on cut slope from previous inspection

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	1. Tank battery signage is missing information and located at entrance		
Corrective Action:	Install sign in correct location and provide correct information		Date: 04/30/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	2. Some staining/paraffin under tank valves		
Corrective Action:	remove all staining		Date: 02/16/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 5		corrective date
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	bear proof dumpster		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	one (1) chemical tank at well head, One (1) chemical tank at tank battery and one (1) portable diesel tank at well heads		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	injection pump in a building		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	Two (2) braden heads are tied into sales and Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Portable air compressor for pressure testing lines		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:	one (1) tank is heated and are in a shared containment with two (2) of the produced water tanks				
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	8	300 BBLs	STEEL AST		,
Comment:	two (2) tanks are is a seperate containment with condensate tanks				
Corrective Action:				Date:	

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	291065	Type:	WELL	API Number:	045-14284	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291066	Type:	WELL	API Number:	045-14285	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291067	Type:	WELL	API Number:	045-14286	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291072	Type:	WELL	API Number:	045-14289	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291073	Type:	WELL	API Number:	045-14290	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	296414	Type:	WELL	API Number:	045-16011	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	296415	Type:	WELL	API Number:	045-16012	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	301818	Type:	WELL	API Number:	045-18286	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 301819 Type: WELL API Number: 045-18287 Status: XX Insp. Status: XX

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 3. Location still shows signs of lack of stabilization on cut slope from previous inspection

Corrective Action: Maintain All BMP's

Date: 01/04/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702260	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5343550