

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/26/2021

Submitted Date:

01/28/2021

Document Number:

700405207

FIELD INSPECTION FORM
 Loc ID 315691 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|---------------------------------|------------|
| Energy, Foundation | | regulatory@foundationenergy.com | Regulatory |
| Thompson, Bud | | BLThomps@BLM.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 231356 | WELL | SI | 05/01/2020 | GW | 103-09026 | RANGELY SOUTH FED 9-4-1-102 | SI |

General Comment:

A routine inspection identified the following compliance issues:

- 1) Provide bradenhead access. Photo 2. Complete by 2-28-2021.
- 2) Install well sign. Photo 5. Complete by 3-30-2021.

This is a summary of inspection report 700405207.

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Missing well sign. Sign frame is present. | | |
| Corrective Action: | Install well sign. | Date: | 03/30/2021 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|-----------------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Telemetry. | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead access is not present. | | |
| Corrective Action: | Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow. | Date: | 02/28/2021 |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|----------|---|----------|------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|---|-------|
| PRODUCED WATER | 1 | <50 BBLs | FIBERGLASS AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | 40 bbl | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | | | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Venting: | | | | | | |
| Yes/No | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Inspected FacilitiesFacility ID: 231356 Type: WELL API Number: 103-09026 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last recorded production April 2020.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | | | | | | |

Comment: 9" of snow on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402586148 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339661 |
| 700405208 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339657 |