

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19SWSW

Location ID: 335005



Photo #2810 from entrance to location.



Photo #2811 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19SWSW

Location ID: 335005



Photo #2812 Multiple flow line exhaust heating insulation open ended and not capped.