

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #2817 from entrance to location.



Photo #2818 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE

Location ID: 335031



Photo #2819 Flow line exhaust heating insulation open ended and not capped.