

**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SW SW  
Location # 335687**



**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SWSW  
Location # 335687**



**UNOCAL-ENCANA 14D-9D**

**Gas bubbling around surface casing of well.**

**CAERUS PICEANCE LLC**  
**UNOCAL-66S96W 9SWW**  
**Location # 335687**



**UNOCAL-ENCANA 24D-9DRD**

**Gas bubbling around surface casing of well.**

**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SWSW  
Location # 335687**



**UNOCAL-ENCANA 13D-9D**

**Gas bubbling around surface casing of well.**

**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SWSW  
Location # 335687**



**Unmarked deadman.**

**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SWSW  
Location # 335687**



**Deadman marker is broken and inadequate.**

**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SWSW  
Location # 335687**



**Impoundment of storm water behind tank battery.**



**Impoundment of storm water between wells and check dam.**

**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SWSW  
Location # 335687**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SWSW  
Location # 335687**



**No tracking bmps observed for well pad.**

**CAERUS PICEANCE LLC  
UNOCAL-66S96W 9SWSW  
Location # 335687**



**No tracking bmps observed for well pad.**

**No tracking bmps observed for well pad.**