

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/29/2021

Submitted Date:

02/01/2021

Document Number:

700702243

FIELD INSPECTION FORM
 Loc ID 420223 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 950 17TH STREET, SUITE 1900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

23 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420217	WELL	PR	08/29/2012	GW	045-20107	McLin C7	PR
420236	WELL	PR	08/29/2012	GW	045-20112	McLin C2	PR
420279	WELL	PR	03/03/2014	GW	045-20113	McLin C3	PR
420289	WELL	PR	03/30/2012	GW	045-20117	McLin C16	PR
420291	WELL	PR	03/03/2014	GW	045-20118	McLin C5	PR
420329	WELL	PR	10/29/2012	GW	045-20130	McLin C20	PR
420331	WELL	PR	08/29/2012	GW	045-20131	McLin C13	PR
420332	WELL	PR	11/30/2013	GW	045-20132	McLin C15	PR
420333	WELL	PR	08/29/2012	GW	045-20133	McLin C24	PR
420336	WELL	DG	10/08/2019	LO	045-20135	McLin C8	DG
420338	WELL	DG	10/08/2019	LO	045-20136	McLin C17	DG
420340	WELL	PR	08/29/2012	GW	045-20138	McLin C23	PR
420341	WELL	PR	10/29/2012	GW	045-20139	McLin C19	PR
420343	WELL	PR	10/29/2012	GW	045-20140	McLin C18	PR
420344	WELL	PR	08/29/2012	GW	045-20141	McLin C22	PR
420345	WELL	PR	11/30/2013	GW	045-20142	MCLIN C6	PR

General Comment:

COGCC Inspection Report Summary

On Friday 1/29/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa McIn C, at Location # 420223 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. C/A's from previous inspection document # 700701912 have been completed.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage is missing information and located at entrance
 2. Location still shows signs of lack of stabilization from previous inspection
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	CONTAINERS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	1. Tank battery signage is missing information and located at entrance			
Corrective Action:	Install sign in correct location and provide correct information			Date: 04/30/2021
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 14			corrective date
Comment:	All meters calibrated on location within a year.			

Corrective Action:		Date:	
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 14		
Comment:	Seven (7) braden heads are tied into sales and all Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	one (1) tank is heated and all are in a shared containment with produced water tanks				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLs	STEEL AST		,

Comment:	all are in a shared containment with condensate tanks		
Corrective Action:		Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420217	Type:	WELL	API Number:	045-20107	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420236	Type:	WELL	API Number:	045-20112	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420279	Type:	WELL	API Number:	045-20113	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420289	Type:	WELL	API Number:	045-20117	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420291	Type:	WELL	API Number:	045-20118	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420329	Type:	WELL	API Number:	045-20130	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420331	Type:	WELL	API Number:	045-20131	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420332	Type:	WELL	API Number:	045-20132	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	420333	Type:	WELL	API Number:	045-20133	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420336	Type:	WELL	API Number:	045-20135	Status:	DG	Insp. Status:	DG
Facility ID:	420338	Type:	WELL	API Number:	045-20136	Status:	DG	Insp. Status:	DG
Facility ID:	420340	Type:	WELL	API Number:	045-20138	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420341	Type:	WELL	API Number:	045-20139	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420343	Type:	WELL	API Number:	045-20140	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420344	Type:	WELL	API Number:	045-20141	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420345	Type:	WELL	API Number:	045-20142	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Limited storm water inspection due to snow cover 2. Location still shows signs of lack of stabilization from previous inspection						Date: 12/18/2020
Corrective Action: Maintain BMP's						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402587566	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5341122
700702248	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5341117