

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/01/2021

Submitted Date:

02/01/2021

Document Number:

695103930

**FIELD INSPECTION FORM**

Loc ID 308563 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274356	WELL	PR	04/15/2005	GW	071-08231	SAMSON 11-35	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Phone 3: AREA OF IMPACTED SOIL NEAR PRIME MOVER ENGINE SKID UNDER RADIATOR. Phone 4: AREA OF IMPACTED SOIL ACROSS FROM GAS SCRUBBER/SEPARATOR ON COMPRESSOR. IT APPEARS THAT GAS SCRUBBER/SEPARATOR ON COMPRESSOR SKID IS BEING DRAINED ON THE GROUND. Phone 5: AREA OF IMPACTED SOIL NEAR WELLHEAD.

Corrective Action:

COMPLY WITH RULE 906.

Date: 03/03/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

# 1

Comment:

CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

Phone 8: BRADENHEAD IS NOT PLUMBED TO SURFACE.

Corrective Action:

COMPLY WITH RULE 341.

Date: 03/03/2021

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	274356	Type:	WELL	API Number:	071-08231	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Phone 6: APPEARS TO BE ANTIFREEZE IN PRIME MOVER ENGINE SKID. Phone 7: APPEARS TO BE OIL EITHER DRAINED OR LEAKED INTO COMPRESSOR SKID.

Corrective Action: COMPLY WITH THE GENERAL RULES OF THE OIL AND GAS ACT & SB-181. (DO NOT DRAIN ANY NON E&P WASTE IN SKIDS OR ON GROUND REMOVE ANY UNINTENDED LEAKS OF NON E&P WASTE INTO SKIDS IMMEDIATELY UPON DISCOVERY. CA DATE 2-6-21.

Date: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402588788	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342229">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342229</a>
695103931	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342227">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342227</a>