

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2021

Submitted Date:

02/09/2021

Document Number:

696104313**FIELD INSPECTION FORM**Loc ID 416214 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416235	WELL	SI	07/01/2020	OW	123-31313	FURROW USX AB 15-10P	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (416044, 416214).
(Well(s): 2: Shut-In | SI).

Refer to Field Inspection Report doc. #696104311 and/or Location ID #416044
for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Paraffin Inhibitor.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696104311 and/or Location ID #416044 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Iron panel w/ barbed wire.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Iron panel w/ barbed wire.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696104311 and/or Location ID #416044 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Equipment:				
Type: Prime Mover	# 1			corrective date
Comment:	Gas engine drives pumping unit. Shut-down.			
Corrective Action:				Date:

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696104311 and/or Location ID #416044 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	At wellsite. 1: Paraffin Inhibitor pump, drum. Placarded.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.566195,-104.526248
Comment:	Centralized Battery serves 2 Location IDs (416044, 416214). Refer to Field Inspection Report doc. #696104311 and/or Location ID #416044 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 416235 Type: WELL API Number: 123-31313 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Locked-Out, Tagged-Out | LOTO.
COGCC records indicate last production: 11/2018.
SI/TA well per Alternative Mechanical Integrity Assurance Program
(Alternative Program). Doc #02385001 (NOBLE).

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 09/14/2019Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: --

Comment: No record of Brhd test within last 12 months. Refer to Rule 206.
Submit current Brhd test. Comply w/ Rule 206.
Contact COGCC Engineering.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 02/08/2021 at approximately 13:01 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: FURROW USX AB /15-10P Location ID: 416214 Well Name: Furrow USX AB 15-10P API: 05-123-31313 Location County: Weld County, Colorado Weather: Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (416044, 416214). (Well(s): 2: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696104311 and/or Location ID #416044 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/09/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104314	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5348374