

Inspection Photos

Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW

Location ID: 334127



Photo #2852 from entrance to location.



Photo #2853 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW

Location ID: 334127



Photo #2854 Sediment has been transported off location due to plowing.



Photo #2855 Sediment has been transported off location due to plowing.

Inspection Photos

Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW

Location ID: 334127



Photo #2856 Sediment has been plowed into berm and vegetation.



Photo #2857 Sediment has been plowed into berm and vegetation.

Inspection Photos

Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW

Location ID: 334127



Photo #2858 Sediment has been plowed into berm and vegetation.