

**TEP ROCKY MOUNTAIN LLC
AMERICAN SODA-67S96W 2SWSE
Location ID: 334932**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
AMERICAN SODA-67S96W 2SWSE
Location ID: 334932**



Capacity fill in on tank label.



**TEP ROCKY MOUNTAIN LLC
AMERICAN SODA-67S96W 2SWSE
Location ID: 334932**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



Debris on location

**TEP ROCKY MOUNTAIN LLC
AMERICAN SODA-67S96W 2SWSE
Location ID: 334932**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
AMERICAN SODA-67S96W 2SWSE
Location ID: 334932**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Location shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**TEP ROCKY MOUNTAIN LLC
AMERICAN SODA-67S96W 2SWSE
Location ID: 334932**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**