

**Api # : 007-06246**



**Well sign on separator facing access road**

**Inspection Photos**  
**Location Name: Conley 7**  
**API #: 007-06246**



**Combustible material (dead/dry weeds) within 25 feet of fired equipment**



**Reclamation area appears to predominantly weeds and undesirable vegetation**



**Inspection Photos**  
**Location Name: Conley 7**  
**API #: 007-06246**



**Weeds inside secondary containment**



**Storage of materials inside secondary containment, trash**



**Inspection Photos**  
**Location Name: Conley 7**  
**API #: 007-06246**



**Weed/undesirable vegetation in reclamation area and trash/debris**



**Trash/debris**



**Inspection Photos**  
**Location Name: Conley 7**  
**API #: 007-06246**



**Stuffing box leak and over oiling rod oiler**



**Oil leak/exhaust staining**