

Grizzly Operating Miller 5-36 Location # 334962

Feb 9, 2021 at 10:41:31 AM
39.544386,-107.658577 ±31.78m
COGCC



location

Feb 9, 2021 at 10:41:43 AM
39.485868,-107.622086 ±5.50m
COGCC



location

Grizzly Operating Miller 5-36 Location # 334962

Feb 9, 2021 at 10:41:51 AM
39.485868,-107.622086 ±5.50m
COGCC



location

Feb 9, 2021 at 10:46:22 AM
39.485664,-107.622381 ±4.77m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Miller 5-36 Location # 334962



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Miller 5-36
Location # 334962**



**Sediment migration/erosion under combustor
(photo from previous inspection)**



**Sediment migration/erosion under combustor
(photo from follow up inspection)**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Miller 5-36
Location # 334962**



**Sediment migration/erosion under combustor
(photo from follow up inspection)**



**Sediment migration/erosion under combustor
(photo from follow up inspection)**



**Grizzly Operating
Miller 5-36
Location # 334962**



location



location



**Grizzly Operating
Miller 5-36
Location # 334962**



Location/ Lack of stabilization



Lack of stabilization



**Grizzly Operating
Miller 5-36
Location # 334962**



Photo from previous inspection of tracking



Photo from follow up inspection of tracking (chemical truck had just left access road before myself)

