

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/10/2021

Submitted Date:

02/12/2021

Document Number:

700702289**FIELD INSPECTION FORM**
 Loc ID 335120 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10531Name of Operator: GRIZZLY OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291271	WELL	PR	11/20/2007	GW	045-14322	GEISKE 43C-26-692	PR
291273	WELL	PR	11/21/2007	GW	045-14323	GEISKE 42A-26-692	PR
291308	WELL	PR	05/09/2013	GW	045-14330	GEISKE 32B-26-692	PR
291314	WELL	PR	11/24/2007	GW	045-14325	GEISKE 32D-26-692	PR
297963	WELL	PR	05/21/2009	GW	045-17004	GEISKE 41B-26-692	PR
297964	WELL	PR	05/21/2009	GW	045-17005	GEISKE 41A-26-692	PR
297965	WELL	PR	05/15/2009	GW	045-17006	GEISKE 42C-26-692	PR
297966	WELL	PR	05/15/2009	GW	045-17007	GEISKE 42D-26-692	PR
297967	WELL	PR	05/15/2009	GW	045-17008	GEISKE 43D-26-692	PR
297968	WELL	PR	05/18/2009	GW	045-17009	GEISKE 32C-26-692	PR
297969	WELL	PR	05/18/2009	GW	045-17010	GEISKE 42B-26-692	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 2/10/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a follow up inspection at Grizzly Geiski, at Location # 335120 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. The C/A's from previous inspection document # 700701841 have NOT been completed. This location is within a Density Habitat and Wildlife Management Area.

During this inspection the following possible compliance issues were observed:

1. Location still shows signs of lack of stabilization from previous inspection on pad
2. No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Signage is located at tank battery		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 14		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	chemical tanks at well heads		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	300 BBLs	HEATED STEEL AST		,	
Comment:	two (2) tanks are in a separate metal containment					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	291271	Type:	WELL	API Number: 045-14322	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291273	Type:	WELL	API Number: 045-14323	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291308	Type:	WELL	API Number: 045-14330	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	291314	Type:	WELL	API Number: 045-14325	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	297963	Type:	WELL	API Number: 045-17004	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	297964	Type:	WELL	API Number: 045-17005	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	297965	Type:	WELL	API Number: 045-17006	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	297966	Type:	WELL	API Number: 045-17007	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:

Facility ID:	297967	Type:	WELL	API Number:	045-17008	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297968	Type:	WELL	API Number:	045-17009	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	297969	Type:	WELL	API Number:	045-17010	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
Ditches						

Comment: This location is within a Density Habitat and Wildlife Management Area.
 1. Location still shows signs of lack of stabilization from previous inspection on pad
 2. No evidence of tracking control BMP's

Corrective Action: 1. Install or repair required BMPs in order to achieve stabilization on location
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 11/27/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702297	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351637