



39.81501, -108.66638, 6196.4ft, 52°  
02/05/2021 11:13:09 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**C&K 1-6      API: 05-103-07880**  
**Inspection: 700405353**



39.81501, -108.66617, 6183.5ft, 26°  
02/05/2021 11:13:51 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Pump jack gas leak.**

**C&K 1-6      API: 05-103-07880**  
**Inspection: 700405353**





39.81508, -108.66617, 6207.8ft, 321°  
02/05/2021 11:32:51 AM





39.81509, -108.66624, 6190.1ft, 21°  
02/05/2021 11:13:25 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tank.**

**C&K 1-6      API: 05-103-07880**  
**Inspection: 700405353**



39.81502, -108.66597, 6191.6ft, 24°  
02/05/2021 11:14:15 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Meter building & pit.**

**C&K 1-6      API: 05-103-07880**  
**Inspection: 700405353**





39.81497, -108.66614, 6193.4ft, 111°  
02/05/2021 11:24:28 AM



39.81496, -108.66613, 6195.5ft, 192°  
02/05/2021 11:24:40 AM