

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2021

Submitted Date:

02/16/2021

Document Number:

700405390

FIELD INSPECTION FORM

Loc ID 314961 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

Findings:

- 9 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Graves, Jim	970-712-0099	mrinc20@maralexinc.com	Operations Manager
Reid, Jordan	970-563-4000	maralexjr@gmail.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229983	WELL	PR	10/02/1998	GW	103-07642	LOWELL BRADY 23-3A	PR

General Comment:

A follow up inspection of documents:

- 1) 700404032 dated 11-3-2020.
- 2) 700404841 dated 1-5-2021.

The following compliance issues were resolved:

- 1) Blowdown tank sign was completed.
- 2) The casing gage was replaced with a plug eliminating that gas leak.

Additional compliance issues:

- 1) Another gas leak at well. Photos 3 & 4. Complete by 2-10-2021.
- 2) Provide bradenhead access. Photo 3. Complete by 3-19-2021.

The emergency number 970-858-8550 was called on 2-9-2021 @ 10:23a to report the additional gas leak. Aaron returned the inspectors phone call to discuss the leak.

Well is located within in a black bear area, and a Rule 1202.d mule deer migration corridor area.

This is a summary of inspection report 700405390.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Calibrated 4-2020.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Bradenhead access is not present.		
Corrective Action:	Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow.	Date:	03/19/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 229983 Type: WELL API Number: 103-07642 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: 4" of snow on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

